Quality Control

NCR: Y	R: Yes / No WORK ORDER NON-CONFORMANCE / UPDATE												
											QA Closed:	Date:	
Work Orde	er:					DISPOSITION		AGAINST DEPARTMENT/PROCESS					
Part No.  NCR No.			Rework Skid-tube Crosstube Machining Small Fab Use-as-is Thermoforming Finishing Work Order Update Large Fab Composite		Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier		Engineering Quality Other						
Root					Descri	ption of work order update	1	Initial	Act	ion	Sign &		
Cause		Date	Step	Qty		or Non-conformance	Ct	nief Eng	Descr	iption	Date	Verification	QC Inspector
Doc/Data													
Equip/Tooling													
Operator													
Material													
Setup					<u> </u>								
Other			:							-			
Process					ĺ								
Supplier													
Training						<b>3</b> .	1						
Unapproved			<u> </u>										
						F	AUI	LT CATE	GORY			··	
Landi	ng G	Bear			_	General	_	-			-		<b>-</b>
	Ш	Bending				Bend	_	Grain			Ovalized		Pressure/Forced
		Centre No	ot Conce	ntric to	o/s	BOM/Route		Hardwa	re	<u> </u>	Over/Under	tolerance	Temperature/Cure
		Cracks				Broken/Damaged	L	Inspecti	on Incomplete	<u> </u>	Part Incorred	it	Weld
		Crushed/	Crimped			Burrs		Instruct	ions Incomplete/U	Jnclear	Part Lost/Mi	ssing	Wrong Stock Pulled
		Cuffs			L	Contamination		Mainte	nance		Part Moved		
		Heat Trea	it			Countersink	L	Mislabe	eled		Positioned V	/rong	<del>-</del>
	Ш	Inspection	n Strip in	Tube		Cut Too Short		Misread	1		Power Loss/	Surge	Other
٠.		Ripples in	Bend			Drill Holes	L	Offset					
			Drawing		Out of Calibration								

Out of Sequence

Outside Dimensions

DQA:

Date:

Turning Sequence

Wave/Twist in Tube

Finish Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Order ID 107910 \*107910\* October-07-13 8:28:48 AM Item ID: D3121-21 Accept \*N900040100\* Setup Start **Revision ID:** Item Name: Bolt \*40\* **Start Qty:** 40.00 **Start Date:** 10/07/13 **Cust Item ID:** Required Date: 10/21/13 Req'd Qty: 40.00 **Customer:** Reference: Run Process Plan: Date: Tooling: Date: Approvals: Stop SPC (Y/N): Date: Date: Reject Sequence ID/ Operation Tool ID Tool # Plan Accept Reject Set Up/ Number Stamp Work Center ID Qty Qty **Description Run Hours** Code 130 Identify as per dwg & Stock Location: 57235 0.00 \*120\* Packaging 0.00 Memo

0.00

0.00

QC21- Final Inspection - Work Order Release

Memo

Packaging

\*140\*

Quality Control

140

QC

Page 2

Insp.

DQA: Date: **WORK ORDER NON-CONFORMANCE / UPDATE** NCR: Yes / No QA Closed: Date: **DISPOSITION AGAINST DEPARTMENT/PROCESS** Work Order: Water Jet Skid-tube Crosstube Engineering Rework Small Fab Prod. Eng. Coor. Quality Machining Part No. Scrap Thermoforming Finishing Rec/Store/Packaging Other Use-as-is Work Order Update Large Fab Composite Supplier NCR No. Description of work order update Action Initial Sign & Root **Chief Eng** Verification QC inspector Date Step Qty or Non-conformance Description Date Cause Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier

Landing	Gear	General				 _
	Bending	Bend		Grain	Ovalized	Pressure/Forced
	Centre Not Concentric to O/S	BOM/Route		Hardware	Over/Under tolerance	Temperature/Cure
	Cracks	Broken/Damaged		Inspection Incomplete	Part Incorrect	Weld
	Crushed/Crimped	Burrs		Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled
	Cuffs	Contamination		Maintenance	Part Moved	_
	Heat Treat	Countersink		Mislabeled	Positioned Wrong	 _
	Inspection Strip in Tube	Cut Too Short		Misread	Power Loss/Surge	Other
	Ripples in Bend	Drill Holes		Offset		
	Torque Waves in Extrusion	Drawing		Out of Calibration		
Γ	Turning Sequence	Finish	Г	Out of Sequence		

Outside Dimensions

**FAULT CATEGORY** 

Wave/Twist in Tube

Folio

Training Unapproved

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

**Picklist Print** 

October-07-13 8:31:13 AM

Page 1

Work Order ID: 107910

\*107910\*

Parent Item:

D3121-21

\*D3121-21\*

Parent Item Name: Bolt

**Start Date:** 10/07/13

Required Date: 10/21/13

**Start Qty: 40.00** 

Required Qty: 40.00

**Comments:** 

IPP A04.02.09New issueKJ/DS

IPP Rev:B ECN 1060 07-11-12 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Locatio	 Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Śtatus
M303H0.500		Purchased	No	110	f	23.1590	0.0417	2			
*****	E00*						**				

\*M303H0 500\*

303 HEX BAR .500

<b>Location</b>	Loc Qty	Loc Code		
MAT018	23.159			
124761	2.677			
<b>★</b> m126724	20.482		1.8 4	Hr 13/10/18

											DQA:	Date:	
NCR: Y	es/	/ No				<b>WORK ORDER NON-</b> 0	100	NFORM	<b>MANCE / UP</b>	DATE	,		
											QA Closed:	Date:	
Work Orde	sř.					DISPOSITION		AGAINST DEPARTMENT/PROCESS					
WOIR OIG	-''-			-		Rework	ıİ		Skid-tube	Crosstube		Water Jet	Engineering
Part N	۱o.					I I I I I I I I I I I I I I I I I I I			Machining	Small Fab	. Pro	d. Eng. Coor.	Quality
	_				<u> </u>	Use-as-is		Thern	noforming	Finishing	ł	e/Packaging	Other
NCR No.				Work Order Update			Large Fab	Composite		Supplier			
_													
Root		_		_	1	ption of work order update	ı	nitial	•	tion	Sign &		
Cause	$\rightarrow$	Date	Step	Qty	(	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data	Ц												·
Equip/Tooling	Ц				į		1						
Operator							}						
Material							1						
Setup													
Other													
Process													
Supplier													
Training													
Unapproved		:			<u></u>								
						F	AUL	T CATE	GORY				
Landi	ng G	ear				General							
		Bending				Bend		Grain			Ovalized		Pressure/Forced
	П	Centre No	t Concer	ntric to	o/s	BOM/Route	Г	Hardwa	re		Over/Under	tolerance	Temperature/Cure
	$\Box$	Cracks				Broken/Damaged		Inspecti	on Incomplete		Part Incorred	ct	Weld
			Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled			
Cuffs			Contamination		<del>-</del>			Part Moved		-			
	П	Heat Trea	t			Countersink		Mislabe	led		Positioned V	Vrong	
. <del></del>		n Strip in	Tube		Cut Too Short		Misread			Power Loss/	_	Other	

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drill Holes

Drawing

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

DART AEROSPACE LTD	Work Order:	107910
Description: Bolt	Part Number:	D3121-21
Inspection Dwg: D3121 Rev: E		Page 1 of 1


	FIRS	ST ARTICLE II	NSPECT	ON CH	ECKLIST		
		X First Arti	cle	Prot	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments	
0.375	+/-0.010	.376	>		FK-04	Vern.	
0.050 - 0.060	N/A	056	~		h	h,	
0.080	+/-0.010	.080	7		ь	ζ.	
10-32UNF3A	N/A	10-32UNF3A					
Major Diameter	Max: 0.190 Min: 0.184	.1884	7		FK-09	Mic	
Over wire	Max: 0.2146 Min: 0.2123	.2136	>		l,	fi .	
	_						
						•	
							-
	OAS	1	I	<u> </u>			
Measured by:	44	Audited by:	H a	08	Prototype Ap	proval: N/A	

Measured by:	44	Audited by:	D.0	<del>0/\</del> 08	Prototype Approval:	N/A
Date:	13/10/18	Date:	13/10/19	S-83	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	04.02.27	New Issue	KJ/RF	
В	06.03.09	Dwg Rev. updated	KJ/JLM	
С	06.06.14	Dwg Rev. updated	KJ/JLM	
D	08.01.16	Dwg Rev. updated	KJ/EC/DD,	
E	08.07.23	Dimensions updated	KJ/DD	



DESIGN DRAWN BY			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
CHECK	ED	APPROVED	DRAWING NO.	REV. E			
	#		D3121	SHEET 1 OF 10			
DATE			TITLE	SCALE			
07.1	1.07		BRACKET ASSEMBLY	1:2			
Α		02.04.15	NEW ISSUE				
В		03.01.16	ADD RIDGES; ADD MAT'L ADD -141/-143/-144,	PROP; FIX P/N /-145/-146			
С		04.02.17	ADD CLEARANCE; USE -	-241 BEARING			




07.	(.0)	DIACKET ASSEMBLT 1:2
Α	02.04.15	NEW ISSUE
В	03.01.16	ADD RIDGES; ADD MAT'L PROP; FIX P/N ADD -141/-143/-144/-145/-146
С	04.02.17	ADD CLEARANCE; USE -241 BEARING
D	06.05.17	D3121-25 CAP WAS 1.024, NOW 1.000
Ε	07.11.07	ADD TOLERANCE TO 0.032 (DETAIL B)




## D3121-041 BRACKET ASSEMBLY

(REPLACES PREMIER P/N B30-23000-33)



#### / D3121-044 (OPPOSITE) D3121-043 (SHOWN) BRACKET ASSEMBLY

(REPLACES PREMIER P/N B30-23000-37/-38)




D3121-15/-16 BRACKET

#### / D3121-046 (OPPOSITE) D3121-045 (SHOWN) BRACKET ASSEMBLY

(REPLACES PREMIER P/N B30-23000-35/-36)




DESIGN	DRAWN BY	DART AEROS HAWKESBURY, ONTA	
CHECKED	APPROVED	DRAWING NO.	REV. E
4		D3121	SHEET 2 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:2






DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED,	DRAWING NO.	REV. E
4  -	<b>-#</b>	D3121	SHEET 3 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:1:

**DETAIL A:** SLOT DETAIL SCALE 2:1 VIEW ROTATED






SECTION C-C


RELEASED

<u>DETAIL B:</u> RIDGE DETAIL PARTIAL SECTION SCALE 1:20





DESIGN #	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED,	DRAWING NO.	REV. E
4	-#	D3121	SHEET 4 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:1




#### D3121-11 BRACKET

- 1) MATERIAL: 17-4 SS PER AMS 5604/5643 (REF DART SPEC. M17-4-B)
  MIN ULTIMATE TENSILE = 150 ksi
  MIN YIELD TENSILE = 100 ksi
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 5) ENGRAVE DART P/N & LOGO AS SHOWN
- 6) HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005

Copyright © 2004 by DART AEROSPACE LTD



DESIGN	DART AEROSPACE HAWKESBURY, ONTARIO, CAN		
CHECKED	APPROVED.	DRAWING NO.	REV. E
4	<del>  #</del>	D3121	SHEET 5 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:2




### D3121-13 BRACKET (SHOWN) D3121-14 BRACKET (OPPOSITE)

- 1) MATERIAL: 17-4 SS PER AMS 5604/5643 (REF DART SPEC. M17-4-B) MIN ULTIMATE TENSILE STRENGTH = 150 ksi MIN YIELD TENSILE STRENGTH = 100 ksi
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 5) ENGRAVE DART P/N & LOGO AS SHOWN
- 6) HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005



DESIGN #	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED	DRAWING NO.	REV. E
4		D3121	SHEET 6 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:2




# D3121-15 BRACKET (SHOWN) D3121-16 BRACKET (OPPOSITE)

- 1) MATERIAL: 17-4 SS PER AMS 5604/5643 (REF DART SPEC. M17-4-B) MIN ULTIMATE TENSILE = 150 ksi
  - MIN YIELD TENSILE = 100 ksi
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 5) ENGRAVE DART P/N AND LOGO AS SHOWN
- 6) HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005

Copyright @ 2002 by DART AEROSPACE LTD



DESIGN #	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED _	APPROVED	DRAWING NO.	REV. E
4		D3121	SHEET 7 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:2




#### D3121-111 BRACKET

- 1) REPLACES PREMIER P/N B32-23001-11
- 2) MATERIAL: 17-4 SS PER AMS 5604/5643 (REF DART SPEC. M17-4-B)
  MIN ULTIMATE TENSILE = 150 ksi
  MIN YIELD TENSILE = 100 ksi
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHEWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 6) ENGRAVE DART P/N & LOGO IN AREAS SHOWN
- 7) HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005

Copyright @ 2002 by DART AEROSPACE LTD



ſ	DESIGN #	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
Ī	CHECKED	APPROVED.	DRAWING NO.	REV. E
1	#	-#	D3121	SHEET 8 OF 10
ſ	DATE		TITLE	SCALE
	07.11.07		BRACKET ASSEMBLY	. 1:2




Copyright @ 2002 by DART AEROSPACE LTD

7) HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005




DESIGN A DRAWN BY		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED _	APPROVED,	DRAWING NO.	REV. E
#	<b>-#</b>	D3121	SHEET 9 OF 10
DATE		TITLE	SCALE
07.11.07		BRACKET ASSEMBLY	1:2



Copyright © 2002 by DART AEROSPACE LTD

HOLE IN SPIGOT TO BE CONCENTRIC WITHIN 0.005





D3121-21 BOLT (SCALE 1:1)

NONE

4) ALL DIMENSIONS ARE IN INCHES

OTHERWISE NOTED


1) MATERIAL: AISI 303 SS HEX, ANNEALED

3) TOLERANCES ARE PER DART QSI 018 UNLESS

5) BREAK ALL SHARP EDGES 0.005 TO 0.015


0.375

2) FINISH:




#### D3121-17 WASHER (SCALE 2:1)

- 1) REPLACES PREMIER P/N B32-23001-17
- 2) MATERIAL: AISI 303 SS ROUND BAR, ANNEALED (REF DART SPEC. M303R)
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.015



#### D3121-19 BEARING (SCALE 1:1)

- 1) POSSIBLE SUPPLIER: KING BEARING P/N 6000-2ZJ/EM FAFNIR P/N 9100KDD
- 2) ALL DIMENSIONS ARE IN INCHES




#### D3121-23 BEARING (SCALE 1:1)

- 1) POSSIBLE SUPPLIER: SKF P/N 61900-2Z OR KML P/N 6900-ZZ
- 2) ALL DIMENSIONS ARE IN INCHES

## D3121-25 CAP (SCALE 1:1)


- 1) MATERIAL: DELRIN ROD, Ø1.25 (REF DART SPEC. M-DELRIN-R1.250)
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES



D3121-241 BEARING ASSEBLY (SCALE 1:1)

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



TAP 10-32

UNF-3A

0.050 TO 0.060

0.080

(REF DART SPEC. M303H0.500)